# SUUNTO WIRELESS TRANSMITTER QUICK GUIDE

#### **)** Activate





1.





2.





3.







1.





2.







15bar/300psi


3.







### ∧ No connection







#### High pressure



#### **Technical Specifications**

- Operating temperature: 0°C to 40°C / 32°F to 104°F
- Storage temperature: -20°C to +50°C / -4°F to +122°F
- Maximum depth of operation: 150 m / 492 ft (complying with EN 13319)
- Max. diameter: 40 mm / 1.57 in
- Length: 80 mm / 3.15 in
- Weight: 103 g / 3.6 oz
- Resolution: 1 bar / 1 psi
- · Rated working pressure: 300 bar /4000 psi
- Max. allowed pressure: 400 bar / 5800 psi

## The state of the s

#### SUUNTO CUSTOMER SUPPORT

 www.suunto.com/support www.suunto.com/mysuunto

2. AUSTRALIA AUSTRIA CANADA CHINA FINLAND FRANCE GERMANY ITALY JAPAN NETHERLANDS NEW ZEALAND RUSSIA SPAIN SWEDEN

SPAIN SWEDEN SWITZERLAND UK USA +61 1800 240 498 +43 720 883 104 +1 800 267 7506

+86 010 84054725 +358 9 4245 0127 +33 4 81 68 09 26 +49 89 3803 8778 +39 02 9475 1965 +81 3 4520 9417

+31 1 0713 7269 +64 9887 5223 +7 499 918 7148 +34 91 11 43 175 +46 8 5250 0730 +41 44 580 9988

+44 20 3608 0534 +1 855 258 0900

#### SUUNTO

© Suunto Oy 10/2012, 2/2014, 12/2014, 3/2015. All rights reserved. Suunto is a registered trademark of Suunto Oy.

